SCProbond[™] A/CRC

Abrasion and Corrosion Resistant Compound

Description:	SCProbond [™] A/CRC is a trowelable, silicon carbide filled, abrasion and corrosion resistant wear com- pound designed for thick application on badly worn areas or known severe wear locations. The unique formula of A/CRC forms a tough high performance barrier that resists sliding abrasion and chemical attack. A/CRC adheres easily to most metals and cast silicon carbide substrates found in harsh pro- cessing environments					
Ordering Information:	SCProbond A/CRC 3 lb. Kit					
J	SCProbond A/CRC 22.5 lb. Kit					
Product Advantages:	Smooth non-sag consistency					
	Spreads easily, filling holes, gouges and worn areas in one application					
	Can be applied vertically and overhead at $1/2^{\circ}$ with no sag					
	Excellent corrosion resistance to a wide range of chemicals					
	Excellent sliding abrasion wear protection					
Application Guidelines:	Maximum Service Temp 200°F					
	Working Time		15 minutes			
	Functional Cure 7 Hours @ 72ºF-77ºF					
	Mix Ratio		2/1 By Volume			
	*The working time varies according to the temperature of the air, the material, and the surface to which it is applied					
Coverage:	Coverage per pound is 30 in ² (193cm ²) at 0.5 in (1.27cm) thickness.					
Physical Properties:	Appearance:		Soft Paste			
	High Velocity Particle Wear					
	Resistance (Abrasion Loss):	1.91 cm ³	ASTM C 704		
	Hardness Shore Scale:		91D	ASTM D 2240		
	Compressive Strength:		11,900 psi	ASTM D 695		
	Flexural Strength:		8,100 psi	ASTM D 790		
	Lap Shear:		2,550 psi	ASTM D 1002		



Silicon Carbide Products, Inc. 361 Daniel Zenker Drive Horseheads, New York 14845 USA Telephone: +1-607-562-8599 Fax: +1-607-562-7585 Email: scp@scprobond.com



 $\mathsf{SCProbond^{TM}}$ is a trademark of Silicon Carbide Products, Inc. Rev 1

SCProbond[™] A/CRC

Abrasion and Corrosion Resistant Compound

Chemical Resistance:	Sodium Hydroxide Ammonium Hydroxide	Sulfuric Acid< 70% Nitric Acid< 10%			
Surface Preparation:	The surface to be coated must be free of all rust, scale, dirt, dust, grease, oil, release agents, or other contami- nants. Preheat the surface to 100°F to drive off any moisture. For smooth surfaces or where vibration is a con- cern, tack weld an open mesh screen or expanded metal approximately 1/16 to 1/8 inch above the surface. Chip off weld slag.				
Measuring:	Partial kit usage is not recommended.				
-	If you need less than the amount of A/C lowing the mixing ratios shown under t	CRC accurately weigh or measure by volume the resin and hardener fol- ypical characteristics.			
	Do not attempt to "eyeball" the mixture needed				
Mixing:	Empty all the hardener into the resin and thoroughly mix with heavy-duty, slow-speed drill and mixing paddle uniform in color, usually 5 to 7 minutes. Remember, incomplete mixing will result in incomplete curing, soft s and poor performance. If the kit becomes colder than 60°F, preheat the pails in front of a floor heater to a m mum of 90°F. Excessive heat will reduce the work life. Do not heat pails with torch.				
	Do not neat pails with torch.				
Application:	Apply a thin, wet coat to create tack. Repeat applications, building the tack coat to the desired thickness. If a screen or expanded metal is used for reinforcement, push a thick layer through the screen at one end. Spread the				

screen or expanded metal is used for reinforcement, push a thick layer through the screen at one end. Spread the A/CRC to the other end, making sure the surface below is covered.

Cure for a minimum of 7 hours at $77^{\circ}F/25^{\circ}C$ before using the equipment or subjecting A/CRC to media.

SAFETY PRECAUTIONS

Avoid breathing of vapors. Forced local exhaust is recommended to effectively minimize exposure. NIOSH approved, organic vapor respirators and forced exhaust are recommended in confined areas, or when conditions (such as heated polymers, sanding) may cause high vapor concentrations. DO NOT WELD, BURN, OR TORCH ON OR NEAR ANY EPOXY MATERIAL HAZARDOUS VA-POR IS RELEASED WHEN AN EPOXY IS BURNED.

Avoid skin or eye contact. Wash skin with soap and water if contact occurs. If eye contact occurs flush with water for 15 minutes and obtain medical attention. Read and understand all cautions on can labels and safety data sheets before using this material.

WARRANTY AND DISCLAIMER

Silicon Carbide Products, Inc. gives no warranty, express or implied, and all products are sold upon condition that purchasers will make their own tests to determine the quality and suitability of the product. Silicon Carbide Products, Inc. shall be in no way responsible for the improper use and service of the product. The information given in this publication is considered to be accurate and reliable and is provided as a service only. Physical properties shown are typical. Actual properties are dependent on curing conditions and degree of cure. Any information or suggestions given are without warranty of any kind and purchasers are solely responsible for any loss arising from the use of such information or suggestions. No information or suggestions given by us shall be deemed to be a recommendation to use any product in conflict with any existing patent rights. TB# (07/25/17)



Silicon Carbide Products

Silicon Carbide Products, Inc. 361 Daniel Zenker Drive Horseheads, New York 14845 USA Telephone: +1-607-562-8599 Fax: +1-607-562-7585 Email: scp@scprobond.com

